



# CXone Mpower EXPERT

## CONAP-356468：将NVIDIA集群交换机升级到CL 5.1.1后、出现"SwitchUnreachable\_Alert"和"UnsupportedSwitch\_Alert"

<https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-Issues/CONTAP-356468>

Updated: Wed, 22 Apr 2026 07:30:22 GMT

### 问题描述

- 在ONTAP 9.161中、在将NVIDIA集群交换机升级到CUMULUS Linux 5.1.1之后、以太网交换机运行状况监控器(CSHM)可能会引发SwitchUnreachable\_Alert 和UnsupportedSwitch\_Alert
- 负责这些警报的资源是错误的"cumulus"设备名称
- 在CSHM与此错误交换机失去联系后、此条目和警报可能会持续长达7天。

```
hm.alert.raised: Alert Id = SwitchUnreachable_Alert , Alerting Resource = cumulus  
raised by monitor ethernet-switch
```

```
hm.alert.raised: Alert Id = UnsupportedSwitch_Alert , Alerting Resource = cumulus  
raised by monitor ethernet-switch
```