



## CONAP-368955 : cluster ping cluster failed with "larger than PPMTU communication failed on 2 path(s)(集群ping集群失败、并显示"2个路径上的PPMTU通信失败")

<https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-Issues/CONTAP-368955>

Updated: Wed, 22 Apr 2026 07:29:00 GMT

### 问题描述

在Cisco Nexus 3232C升级到RC框架1.12a后、集群ping集群命令失败并显示以下消息。

```
[
Cluster-01 : : *> cluster ping 集群-node Node-02
主机为节点-02
从网络接口表获取地址...
集群集群-01-01_clus1 169.xxx.xxx节点-01 e0a
集群集群-01-01_clus2 169.yyy.yyy.yyy节点-01 e0b
集群集群集群-01-02_clus1 169.zzz.zzz节点-02 e0a
集群集群-01-02_clus2
```

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

基本连接在4个路径上成功

基本连接在0个路径上失败

在4个路径上检测到9000字节MTU：

本地169.aaa.aaa.a.aaa到远程169.xxx.xxx

本地169.aaa.aaa.aa.aaa到远程169.yyy.yyy.yyy

本地169.z.zzz到远程169.xxx.xxx到远程

169.xxx.xxx