



CONTAP-375150: AFF A700、FAS9000: BIOS 10.19 和 LOADER 8.5.0 的增强功能

<https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-Issues/CONTAP-375150>

Updated: Wed, 22 Apr 2026 07:29:12 GMT

问题描述

BIOS 10.19 和 LOADER 8.5.0 适用于 AFF A700 和 FAS9000 系统，包括错误修复和可靠性增强。

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information