



---

## CONTAP-458789: 适用于 S1743 型驱动器的 NA51 FW 版本

<https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-Issues/CONTAP-458789>

Updated: Wed, 22 Apr 2026 09:49:04 GMT

### 问题描述

S1743 固件版本 NA51 是一个维护版本，包括以下改进：

- 性能改进
- 增强产品稳定性
- 一般可靠性改进

ONTAP：

零件号 型号 容量 新固件

-----  
X4032 X4032S174315TNVF 15TB NA51

X4030 X4030S174330TNVF 30TB NA51

---

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information