



# NiCE

---

## CONAP-67156 : 无法为过量提交的精简卷增加大量"percent快照空间"值

[https://kb-cn-stage.netapp.com/on-prem/ontap/Ontap\\_OS/FS\\_Issues/CONTAP-67156](https://kb-cn-stage.netapp.com/on-prem/ontap/Ontap_OS/FS_Issues/CONTAP-67156)

Updated: Thu, 04 Jun 2026 04:41:25 GMT

### 问题描述

使用 `-percent-snapshot-space` 参数运行 `volume modify` 以增加快照预留空间的百分比失败、并显示错误：  
Error: command failed: Unable to set volume attribute "percent-snapshot-space" for volume "<VOLUME>" on Vserver "<SVM>".  
Reason: Insufficient space on volume "<VOLUME>" to complete operation.