



CONVA-78059 : 卷重新挂载和重新平衡导致内存数据不一致

https://kb-cn-stage.netapp.com/on-prem/ontap/Ontap_OS/FS_Issues/CONTAP-68059

Updated: Wed, 22 Apr 2026 08:33:50 GMT

问题描述

SVMDR复制间歇性失败、并显示错误：

[Failed to set Exported Snapshot copy vserverdr.Snap照.XYZ.2024-12-31_535959 on volume SVM : volume. (Volume Busy)]