



NiCE

CONTAP-255938：在双节点 MetroCluster 配置中的 ONTAP 升级期间报告 DR 配置复制错误

https://kb-cn-stage.netapp.com/on-prem/ontap/Ontap_OS/OS-Issues/CONTAP-255938

Updated: Thu, 04 Jun 2026 02:48:11 GMT

问题描述

升级到 9.14.1Px 后数据 vservers 进入降级状态，原因是 [Apply failed for Object: publickey_ui Method: baseline.Reason: "application" is a required field]