



CONTAP-383134 : 由于 EKM , 切换失败

https://kb-cn-stage.netapp.com/on-prem/ontap/Ontap_OS/OS-Issues/CONTAP-383134

Updated: Wed, 22 Apr 2026 08:47:50 GMT

问题描述

- 正在使用外部密钥管理器(EKM)。
- 切换或切换模拟因加密问题而失败：

```
::> metrocluster operation show
Operation: switchover-simulate
State: failed
Start Time: <date & time>
End Time: <date & time>
Errors: Failed to validate the node and cluster components before the switchover
operation.
Cluster_Name (fatal): Processing Subsystem (SO Check KMIP configuration is in sync
between local and remote cluster) encountered an unknown error.
```

- 所有节点都有合适的密钥服务器，可用于
`security key-manager external show-status`