



COOTP-63314 : 双节点无交换机A400集群在交叉连接时可能会遇到远程数据访问问题

https://kb-cn-stage.netapp.com/on-prem/ontap/Ontap_OS/OS-Issues/CONTAP-63314

Updated: Wed, 22 Apr 2026 08:25:45 GMT

问题描述

We see the following EMS message in logs. If the message repeats every few minutes, it might indicate a problem in the cluster interface configuration or the physical cabling of the switchless cluster. If two-node switchless A400 cluster ports are cross-cabled, remote data access might have intermittent issues due to session establishment failures. Additional issues on the cluster may arise due to the cross-cabled ports, and thus identifying and resolving the cross-cabled ports is the first step prior to resolving any other issues on your cluster.

```
[cluster01-01: kernel: csm.homePortInfoUnexpected:notice]: CSM reports unexpected information for cluster LIF ID "1023" (home port: "e3b", remote device ID: "e3a"). Intermittent timedout alerts for NFS mounts on the servers. cluster02-02 ERROR Nblade.nfsConnResetAndClose: Shutting down connection with the client. Vserver ID is 4; network data protocol is NFS, Rpc Xid 0x0; client IP address:port is 10.120.10.19:25368. local IP address is 10.120.10.18; reason is Idle Timeout, closing connection.
```