



CONAP-66384 : ATto网桥错误地报告为不安全

https://kb-cn-stage.netapp.com/on-prem/ontap/Ontap_OS/RAID_Issues/CONTAP-66384

Updated: Wed, 22 Apr 2026 07:30:36 GMT

问题描述

ATTO Bridges 错误地报告称不安全，但实际上它们是安全的

例子：

[

::> 系统桥显示

是监视器管理的还是桥接的

桥符号名称 监控状态 按供应商型号 桥 WWN 安全

```
-----  
ATTO_2000000000000000 Bridge1A  
true ok 带内 Atto FibreBridge 7600N 2000000000000000 false  
ATTO_2000000000000040 Bridge1B  
true ok 带内 Atto FibreBridge 7600N 2000000000000040 false  
ATTO_20000000000000c0 Bridge2A  
true ok 带内 Atto FibreBridge 7600N 20000000000000c0 false  
ATTO_20000000000000b00 Bridge2B
```

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

true ok 帯内 Atto FibreBridge 7600N 200000000000b00 false
]