



## CONAP-85802：磁盘可能会报告不正确的开机时间

[https://kb-cn-stage.netapp.com/on-prem/ontap/Ontap\\_OS/RAID\\_Issues/CONTAP-85802](https://kb-cn-stage.netapp.com/on-prem/ontap/Ontap_OS/RAID_Issues/CONTAP-85802)

Updated: Wed, 22 Apr 2026 07:31:26 GMT

### 问题描述

接通时间可能会在大约6.7年后转至零、从而导致接通时间显示不正确。要更正此错误、请将ONTAP更新为此缺陷的修复程序、并从

[\[https://mysupport.NetApp.com/site/do-ve-Firmware\]](https://mysupport.NetApp.com/site/do-ve-Firmware)

将驱动器固件升级为最新版本。此问题描述会影响包含以下型号字符串的驱动器型号。下面的特定型号仅为示例。请参阅所有型号类型的驱动器固件页面：

model\_string -单个示例型号驱动器：

HAKPE X316\_HAKPE06TA07 (

如果您的型号包含**HAKPE**、则此型号会受到影响、并可

从此修复中受益) **HARIH X316\_HARIHIB06TA07** (如果您的型号包含**HCBX318\_HCBBHE\_HCB8BE\_HCBB0823**、则此型号会受到此修复中

受益

)

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information