



CXone Mpower EXPERT

新分配的 LUN 不可见，并出现错误："The legacy I/O bus instance number exceeded the maximum allowed bus number limit of 256"

https://kb-cn-stage.netapp.com/on-prem/ontap/da/SAN/SAN-KBs/Newly_assigned_LUN_not_visible_wi...

Updated: Wed, 22 Apr 2026 07:30:18 GMT

适用场景

- HP-UX 11.31
- ONTAP 9
- AFF-A700

问题描述

- 新分配的存储 LUN 在主机端的 `ioscan` 上不可见，并且缺少设备路径。
- 此外，主机端的系统日志文件还会报告以下警告消息：

```
Jan 21 14:47:03 ndrctm01 vmunix: WARNING: The legacy I/O bus instance number  
exceeded the maximum allowed bus number limit of 256. All I/O bus devices  
attached to the bus that have instance
```

Jan 21 16:44:05 ndrctm01 vmunix: WARNING: The legacy I/O bus instance number exceeded the maximum allowed bus number limit of 256. All I/O bus devices attached to the bus that have instance numbers greater than 255 are not CLAIMED.