



---

## CONTAP-343214: ONTAP 集群节点意外重启

<https://kb-cn-stage.netapp.com/on-prem/ontap/da/NAS/NAS-Issues/CONTAP-343214>

Updated: Wed, 22 Apr 2026 08:25:41 GMT

### 问题描述

ONTAP 集群节点意外重启：

```
page fault (supervisor write data, page not present) on VA 0cs:rip
```

```
0x20:0xfffffffffa38f3215 rflags 0x10286 in SK process nblade2 on release 9.15.1P8 (C)
```