



# CXone Mpower EXPERT

## CFBMC-6884：拔掉电源线时，AFF A70 "system controller environment show" 将 PSU 报告为 "GOOD"

<https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-Issues/CFBMC-6884>

Updated: Wed, 22 Apr 2026 07:28:42 GMT

### 问题描述

从 PSU 中拆除电源线在环境中显示"良好"状态。示例：

```
::> event log show
Time Node      Severity Event
-----
... node_name NOTICE   monitor.chassisPowerSupply.degraded: Chassis power supply 1
is degraded: PSU1 In Curr is Unreadable
... node_name NOTICE   monitor.chassisPowerSupply.degraded: Chassis power supply 1
is degraded: PSU1 In Volt is Unreadable
::> system controller environment show
Node      FRU Name State
-----
node_name PSU2 FRU GOOD
node_name PSU1 FRU GOOD
```

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

...